How to setup an integrated line display on the XR7

Summary:

How to setup an integrated line display on the XR7

Solution:

In Setup / POS / Devices, add the **Radiant 2x20** and then choose **RSLD.COM8** for the OPOS name.