

Printer Dip Switch Settings for Serial Communications

Summary:

Printer Dip Switch Settings for Serial Communications (Bixolon 350Plus, Epson TM88, Epson TM-H6000III

Solution:

See attached document for guide to setting DIP switch settings correctly for serial printers.

If the printer is printing gibberish or all question marks (?) this is most likely due to incorrect DIP switch settings.

Online URL: <https://counterpoint.knowledgebase.co/article.php?id=480>