Lines wrapping on Crystal Receipts in Legacy Device Framework

Summary:

Lines wrapping on Crystal Receipts (.rpt) in Legacy Device Framework.

Cause:

Device is not setup properly in CPSQL.

Solution:

- In **Setup / Point of Sale / Devices**, click **Configure** for the OPOS receipt printer.
- Select the Force CR/LF box on the POS Printer window.

Online URL: https://counterpoint.knowledgebase.co/article.php?id=5