

Printer Dip Switch Settings for Serial Communications

Article Number: 480 | Rating: Unrated | Last Updated: Wed, Jul 15, 2015 at 12:04 PM

Summary: Printer Dip Switch Settings for Serial Communications (Bixolon 350Plus, Epson TM88, Epson TM-H6000III) **Solution:** See attached document for guide to setting DIP switch settings correctly for serial printers. If the printer is printing gibberish or all question marks (?) this is most likely due to incorrect DIP switch settings.

Posted - Mon, Aug 25, 2014 at 2:00 PM. This article has been viewed 4528 times.

Online URL: <https://counterpoint.knowledgebase.co/article-480.html>