

Article Number: 1226 | Rating: 5/5 from 1 votes | Last Updated: Tue, Sep 10, 2019 at 9:40 AM

Summary: Printer prints garbage when changing logos multiple times in Counterpoint 8.5.6.2 device management, causing the logo to be distorted. **Cause:** Known issue in 8.5.6.2 Service Pack with the Epson ESCPOS printer driver. **Solution:** The workaround is to change the logo with a different logo image in Setup/PS/Devices and do a Device Test, then change it back again with the correct/original logo and save.

Posted - Tue, Apr 30, 2019 at 12:07 PM. This article has been viewed 1796 times.

Online URL: <https://counterpoint.knowledgebase.co/article-1226.html>